1. IDE 右下角编码区域, 鼠标右键单击



Change Encoding (Matches Autodetect)



3. 右键单击目标工程,选择 open containing folder, 打开工程所在目录

4. 在工程下查看是否有这个文件,有就删除

📙 🛛 🛃 🗖 🖛 🗆 .settings								-	×
文件主页共享	查看								~ 🕐
■ 预览窗格 导航窗格 ■ 详细信息窗格	■ 超大图标 ■ 大图标 副 中图标 副 小图标 ■ 大图标 副 中图标 副 小图标 ■ 列表 ■ 详细信息 ■ 平端 ■ 内容			项目复选框 文件扩展名 隐藏 隐藏的项目 所进项目	φ				
窗格	布局		当前视图	显示/隐藏					
← → ヾ ↑ 📙 ゝ 此	电脑 > 本地磁盘 (C:) > MRS_DATA >	workspa	ce > CH32V307VCT6fff > .settings				v ⊙	搜索".settings"	P
🛄 此电脑		^	名称 ^	修改日期	类型	大小			
🧊 3D 对象			🔮 language.settings.xml	2024/9/2 10:59	XML 文档	2 KB			
🚪 视频			org.eclipse.core.resources.prefs	2024/9/2 11:00	PREFS 文件	1 KB			
■ 図片									
🗎 文档							•		
👆 下载		- 11							
♪ 音乐									
重 桌面									
🏪 本地磁盘 (C:)									
🕳 新加卷 (D:)									
🔜 新加卷 (E:)									
新加卷 (F:)									
🖶 CD 驱动器 (G:) Mac	KMLink	~							
2 个项目 选中 1 个项目	238 字节								111

5. 在 IDE 中, 右键关闭工程

CH32V307VC1	T6fff		8 * Copyright	(C) 2021 Nanjing
> 🗊 Includes > 避 Core		New Add	>	This software (m pller manufacture
> 🔑 Debug > 🔑 Ld		Copy Paste	Ctrl+C Ctrl+V	5TEM_CH32V30x_H 5TEM_CH32V30x_H
> 😂 Startup	×	Remove Move	Delete	isplus (
h ch32v3		Rename	F2	
c ch32v3 h ch32v3	≛ ≪	Build Project Clean Project	F7	2_t SystemCoreClc ported_Functions
.c system	<u>\$</u>	Refresh Close Project	61	SystemInit(void); SystemCoreClockUp
CH32V30	ch.	Index	>	ısplus
6. 随后打开工程	-0125 T6fff	Debug As	, 8 **********************************	***** * ******************************
	New Add		> pht (c) 20 , ion: This ntroller	21 <u>Nanjing Qinheng Micr</u> software (modified or n manufactured by <u>Nanjing</u>
	Copy	/	Ctrl+C passage	

	Add	ontroller manufactured by Nanjing						
	Сору	Ctrl+C						
Ē	Paste	Ctrl+V	DEBUG H					
×	Remove	Delete						
	Move		cplusplus					
	Rename	F2	C" {					
	Open Project							
-	Debug As	>	<pre>Kch32v00X.h> Kstdio_b></pre>					
	Include/Exclude From Build							
2	Import		EBUG_UART1_NoRemap	1	//Tx-PD5			
4	Export		EBUG_UART1_Remap1	2	//Tx-PD6			
	Download	、 、	EBUG_UART1_Remap2	3	//Tx-PD0			
	Download		EBUG_UART1_Remap3	4	//Tx-PC0			
1	Code Format		EBUG_UART1_Remap4	5	//Tx-PD1			
	Compare With	、 、	EBUG_UART1_Remap5	6	//Tx-PB3			
	compare with		EBUG_UART1_Remap6	7	//Tx-PC5			
	Restore from Local History		EBUG UART1 Remap7	8	//Tx-PB5			

7. 检查编码设置是否是 UTF8

SCH32V307V		New	>	(c) 2021 Naniing Oinbeng Microelectronics Co.
		Add	>	: This software (modified or not) and binary a:
		Conv	Chall C	coller manufactured by <u>Nanjing Qinheng Microel</u>
		Сору	Cul+C	***************************************
		Paste	Ctri+v	BUG_H BUG_H
	*	Remove	Delete	
		Move		usplus
		Rename	F2	ť
	۲	Build Project	F7	
	1	Clean Project		32v00X.h>
	æ	Refresh	F5	dio.h>
	-	Close Project		
				tf Definition */
		Index	>	G UARTI NOREMAP I //Tx-PD5
	1	Debug As	>	G UART1 Remap2 3 //Tx-PD0
	100	Include/Exclude From Build		G UART1 Remap3 4 //Tx-PC0
	land P			-G_UART1_Remap4 5 //Tx-PD1
	è	Import		G_UART1_Remap5 6 //Tx-PB3
	4	Export		G_UART1_Remap6 7 //Tx-PC5
		Download	>	G HARTI Remark 9 //Tx-PB5
	i=	Code Format		- GARTI_Remapo
		code romat		int function only for V005,V006,V007,M007 serie
		Compare With	>	CH32V005) defined(CH32V006) defined(CH32'
E Outli 😚 🗐		Restore from Local History		C TINDTO M-D 10 //T- D17
	**	Rebuild		
		Save as Project Template	Ctrl+Shift+X	E Console 🕮 🛷 Search 🍡 Breakpoints 🚸 Debug
n outline is not av		Open Containing Folder		t this time.
		Open MRS Console	Ctrl+Shift+V	
		Concheck		
		opponent		
		Open in New Window		
		Properties		

V Properties for CH32V307	/CT6fff	_		×
type filter text	Resource		• =	
 Resource C/C++ Build C/C++ General cppcheclipse MCU Project Natures Project References Refactoring History Run/Debug Settings 	Path: /CH32V307VCT6fff Type: Project Location: C:\MRS_DATA\workspace\CH32V307VCT6fff Last modified: September 2, 2024 at 10:59:52 AM Text file encoding Inherited from container (UTF-8) Other: UTF-8 Store the encoding of derived resources separately New text file line delimiter Inherited from container (Windows) Other: Windows	faults	Арр	ly
?	Apply and Close	se	Cancel	